



## BMPs for Waste Haulers

The Waste Haulers Best Management Practices (BMP) Program is a program designed to address the discharge of used grease and septage/port-o-let waste into the sewer system. Because of this potential, the City-Parish requires the waste haulers to obtain a Pretreatment Permit. The general permit is regulated by the policies and BMPs found in this document.

### Program Details and Documents

#### Required Best Management Practices:

##### Grease Trap Waste:

- Train Employees at least once a year, maintain a log of training records.
- Keep manifest data from the past three (3) years.
  - Check that the owner/manager of restaurant has signed manifest before leaving site.
- Clean grease trap completely using proper procedures.

##### Septage/Port-o-let Waste:

- Train Employees at least once a year, maintain a log of training records.
- Keep manifest data from the past three (3) years.
  - Check that the owner/manager has signed manifest before leaving site.
- Use proper procedures when removing waste.